



Figure 4.
Crooked River Gap Fencing Environmental Assessment
South Fork Fence Locations

Based on USGS 1:24,000 Sand Hollow and Liggett Table quadrangles.

	Existing fence		Proposed Fence Construction		Reconstruct Damaged Fence
#	Fence Segments		Bureau of Land Management		Private Land

